

Vanasse Hangen Brustlin, Inc.

Figure 3-16 Sheet 1 of 2

1997 Existing Conditions
AM Peak Hour