Routine Roadway Maintenance
M313-31, Tilton
20 scale
3/30/2016
By D. Silvia



Work Description
Replacing a failing 24" x 40' CMP
with a 24" x 40 HDPE plastic pipe.

LEGEND

TYPE OF VETLAND IMPACT	PERMANENT IMPACT
N.H.V.B. (NON-VETLAND)	
N.H.V.B. & A.C.O.E. (VETLAND)	

N.H.V.B. - NEW HAMPSHIRE VETLANDS BOARD
A.C.O.E. - ARMY CORP. OF ENGINEERS

VETLAND DESIGNATION NUMBER

VETLAND IMPACT LOCATION

VETLAND MITIGATION AREA

TEMPORARY IMPACTS

MITIGATION

OHW ORDINARY HIGH WATER

TOB TOP OF BANK

TBZ TIDAL BUFFER ZONE

TOB OHW TOP OF BANK & ORDINARY HIGH WATER

SHOWN SMALLER THAN ACTUAL SIZE

VETLAND DESIGNATION	USFWS VETLAND CLASSIFICATION	LOCATION	AREA (S.F.)		
			N.H.V.B. (NON-VETLAND)	N.H.V.B. & A.C.O.E. (VETLAND)	TEMPORARY IMPACTS
1	PEM1E	A			100
2	PEM/PSS1E	B			100
		C			
		D			
		E			
		F			
		G			
		H			
		I			

PERMANENT IMPACTS: S.F.
TEMPORARY IMPACTS: 200 S.F.

TOTAL IMPACTS: 200 S.F.