

Appendix H - ADA Survey Summary - NHDOT owned Park and Rides, Bus Terminal, Rail Trail Parking							
Location	ADA compliant?	Total Spaces	Total Accessible	Van Accessible	Bus Terminal?	ADA Discrepancies	Comments
Andover Rail Trail	No	24	2	2	No	No signage. No accessible path to trail.	Need (2) R7-8, (1) R7-8a, accessible path to Rail Trail.
Boscawen	No	42	2	1	No	No wheelchair pavement markings, 2.7% slope, missing sign, sign that was there read "handicapped".	Need (2) R7-8, (1) R7-8a
Bow	Yes	62	3	1	No		
Canterbury	No	10	1	1	No	4% slope	
Chesterfield	No	37	2	1	No	Missing R7-8a, signs faded	Need (2) R7-8, (1) R7-8a
Concord I89	No	100	4	1	No	Van access aisle is 64"w, needs to be 96"w.	
Concord I93	No	342	8	0	Yes	Needs signage at each space, van access aisle is 84"w, needs to be 96"w.	Need (8) R7-8
Dover NH 16 C&J	Yes	440	9	2	Yes		
Epping	No	246	8	1	bus stop	Needs another van accessible space, markings and signs faded. No posted bus schedule.	Need (8) R7-8, (2) R7-8a
Grantham	Yes	52	2	1	shelter		
Hampstead	No	unknown	4	2	No	3% slope.	Unknown spaces due to faded paint. One extra van sign. "Handicapped" verbiage.
Hampton	No	103	5	1	No	Van access aisle is 87"w, needs to be 96"w.	
Hillsboro	Yes	133	5	2	No	3% slope in few areas.	Spaces barely visible due to faded paint.
Hooksett	No	Unknown	Unknown	Unknown	No	No striping or signs.	
Londonderry Exit 4	Yes	250	9	4	Yes		
Londonderry Exit 5	Yes	750	17	4	Yes		
Lyme	Yes	35	2	1	No		Need (1) R7-8a van sign
Nashua Exit 7	Yes	48	3	2	No		"Handicap" verbiage. Signs partially knocked over, one unreadable, blocked by leaves and trash.
Nashua Exit 8	Yes	275	7	3	Yes		If cars pull too far forward access aisle can be blocked. "Handicap" verbiage.
New Hampton	Yes	108	4	1	No		
New London	Yes	132	8	6	Yes		
Plaistow	No	267	11	2	No	Phone is 6" too high.	Disused bustop has tree blocking entrance.
Portsmouth Transportation Center	Yes	1210	29	9	Yes		Overflow lot missing two van signs, terminal missing two van signs, side of terminal missing three van signs.
Randolph Rail Trail lot	No	unknown	0	0	No	No signed or marked spaces. No accessible path to trail.	Needs signage, marked spaces and accessible path to Rail Trail.
Rochester	Yes	199	8	4	Yes		Two glass panels broken on shelter. No posted bus schedule.
Salem	No	474	9	3	Yes	Van access aisles 69"w - need to be min 96"w	
Tilton	Yes	unknown	4	1	No		Could not count total spaces due to faded striping. Signs faded.
Warner	No	24	1	1	No	3% slope in few areas.	Need R7-8a van sign.
Windham	No	67	2	2	shelter	Accessible spaces far from shelter, should be closest. 6% running slope, should be 2% or less.	Shelter inaccessible due to asphalt curb. Sign post crooked. Need (1) R7-8a van sign.