



Andover 12805 Maple St.
Original wooden highway bridge rebuilt with satisfactory results.



Andover 12806 Valley Road
Original wooden highway bridge rebuilt with satisfactory results.



Andover 12804 (2001) Lawrence St.
Highway bridge removed and replaced with small arch culvert.

Franklin 12938 (2007) Chance Pond Rd.
Railroad bridge removed with resulting long steep grades.

Andover P-4383 (1998) NH 11
Highway bridge removed with NH 11 crossing relocated to new location 2500 feet westerly with high-speed at-grade highway crossing.

Andover P-4383 (1998) Plains Road
Railroad bridge removed to create at-grade crossing of Plains Road with loss of typical horizontal rail trail alignment. (New NH 11 at-grade crossing shown in picture also.)

Andover 14169 (2010) US 4
Highway bridge removed. Replaced with satisfactory culvert with approximately 23-foot horizontal opening



SALISBURY

ANDOVER

FRANKLIN