

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Action Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Acworth

0010

113/064	NH123A	over	BOWERS BROOK	Nov 2008	29.4	NHDOT	Jack	27.3	17	1	E2	Y	1915
			<b>State Redlist</b>	Not Applicable	Over			420, 2005	24.0	Rural Min. Collector	Primary-DOT Maintained		
			Serious Condition. Additional damage during 2005 flood event. Was listed in program for 2007, \$600,000.00. Temporary flood repairs done by Bridge Maintenance.			Replace		In the Program			\$1,000,000.00	2018	

## Alstead

0050

060/159	NH123	over	COLD RIVER	Nov 2008	61.8	NHDOT	CRF	40.0	68	1	Fed Br	NPR	Y	1958
			<b>State Redlist</b>	Structurally Deficient	Over			1900, 2002	30.0	Rural Mjr. Collector	Primary-DOT Maintained			
			Temporary Bridge in place, construction underway.			Replace		In the Program			\$2,042,090.00	2008		
073/163	NH123A	over	WARREN BROOK	Nov 2008	56.0	NHDOT	CTB	29.1	34	1	Fed Br	C1	Y	1935
			<b>State Redlist</b>	Structurally Deficient	Over			2400, 2005	26.7	Rural Min. Collector	Primary-DOT Maintained			
			Deck Poor. Additional damage during 2005 flood.			Rehab		To be addressed by Bridge Maintenance				WTP		

## Andover

0080

050/093	NH 11	over	BLACKWATER RIVER	Mar 2009	69.6	NHDOT	IB-C	48.5	124	2	Fed Br	NPR	Y	1959
			<b>State Redlist</b>	Structurally Deficient	Over			4900, 2006	46.0	Rural Minor Arterial	Primary-DOT Maintained			
			Deck Poor. Pier repaired 2005 by Bridge Maintenance.			Rehab		Needs to be added to the Program			\$2,000,000.00			
058/103	NH 11	over	US 4,NHRR(ABD)	Mar 2009	33.5	NHDOT	IB-C	34.5	264	6	Fed Br	NPR	Y	16.67 1959
			<b>State Redlist</b>	Structurally Deficient	Over			4900, 2006	28.0	Rural Minor Arterial	Primary-DOT Maintained			
					Road Under			4900, 2003	-3.3	Rural Minor Arterial	Primary-DOT Maintained			
			Deck Serious. Bids received.			Remove		In the Program			\$3,046,961.00	2009		
179/146	VALLEY ROAD	over	NHRR(ABD)	Nov 2008	67.1	NHDOT	TB	16.5	90	5	Fed Br	15	Y	23.17 1930, 2002
			<b>State Redlist</b>	Not Deficient	Over			40, 2005	15.2	Rural Local	Municipal Highway			
			Low Capacity, Posted 'Weight Limit 15 Tons'. Bridge Maintenance rehab completed 2002.					Monitor and Keep in Service						

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Bartlett

0170

<b>232/147</b>	US302,NH 16 over THORN HILL BROOK	Nov 2008 *	41.0	NHDOT	MP	88.6	12	1	NPR Y	1960
	<b>State Redlist</b>	Not Applicable	Over	NHS	13300, 2006	44.0	Rural Princ. Arterial	Primary-DOT Maintained		
	Pipe in Poor condition.			Rehab	To be addressed by Bridge Maintenance			WTP		

## Bedford

0190

<b>090/065</b>	NH101 over PULPIT BROOK	Aug 2008 *	48.3	NHDOT	CP	42.5	13	2	NPR Y	1936
	<b>State Redlist</b>	Not Applicable	Over	NHS	29000, 2006	40.0	Rural Princ. Arterial	Primary-DOT Maintained		
	Settlement of concrete pipes, gaps between segments.			Replace	To be addressed by Bridge Maintenance			WTP		

<b>189/121</b>	US 3 over FEE TPK	Mar 2009	28.8	Turnpike Bureau, NHDOT	IB-C	41.5	150	2	Fed Br	NPR Y	16.50	1955
	<b>State Redlist</b>	Structurally Deficient	Over	NHS	14000, 2005	30.0	Urban Expressway	Primary-DOT Maintained				
			Road Under	NHS	19000, 2004	55.8	Urban Expressway	Primary-Turnpike Maint.				
	Deck and Substructure Poor.			Replace	In the Program			\$14,093,000.00	2013			

## Bennington

0210

<b>093/094</b>	BMRR(ABD) over ANTRIM ROAD	Nov 2008	N/A	NHDOT	TB	9.8	19	1	NPR Y	13.42	1930
	<b>State Redlist</b>	Not Applicable	Over		0, 2005	9.8	Rural Local	Undetermined / NA			
			Road Under		2800, 2005	16.4	Rural Local	Municipal Highway			
	Rail line not in service, Severe Overheight Damage, Poor Condition.			Rehab	To be addressed by Rail and Transit			WTP			

## Bow

0270

<b>135/160</b>	I-93,FEE TPK SB over I-89,TURKEY RIVER	Dec 2008	32.7	Turnpike Bureau, NHDOT	IB-C	35.8	244	5	Fed Br	NPR Y	18.44	1957, 1980
	<b>State Redlist</b>	Structurally Deficient	Over	NHS	62000, 2003	30.0	Urban Interstate	Interstate (Turnpike)				
			Road Under	NHS	40000, 2003	-3.3	Urban Interstate	Interstate Highway				
	Deck and Substructure Poor. Project scope reduced to rehab.			Rehab	In the Program			\$2,500,000.00	2010			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Bow

0270

136/160	I-93,FEE TPK NB over I-89,TURKEY RIVER	Dec 2008	52.5	Turnpike Bureau, NHDOT	IB-C	47.8	244	5	Fed Br	NPR Y	16.40	1957, 1980
	<b>State Redlist</b>	Structurally Deficient	Over	NHS 30300, 2004		42.0	Urban Interstate			Interstate (Turnpike)		
			Road Under	NHS 17000, 2004		-3.3	Urban Interstate			Interstate Highway		
	Deck and Substructure Poor. Project scope reduced to rehab.			Rehab	In the Program					\$2,500,000.00	2010	

## Canaan

0360

124/103	CANAAN STREET over MASCOMA RIVER	Nov 2008	56.0	NHDOT	CRF	31.0	38	1	Fed Br	NPR Y		1936
	<b>State Redlist</b>	Structurally Deficient	Over			760, 2005	27.4	Rural Min. Collector		Secondary-DOT Maintained		
	Poor Condition.			Replace	Needs to be added to the Program					\$1,200,000.00		

## Chesterfield

0450

080/120	BROOK STREET over CATSBANE BROOK	Nov 2008	77.2	NHDOT	IB-C	26.7	41	1	Fed Br	C2 Y		1950
	<b>State Redlist</b>	Structurally Deficient	Over			550, 2005	24.5	Rural Min. Collector		Secondary-DOT Maintained		
	Deck Poor.			Rehab	To be addressed by Bridge Maintenance					\$1,200,000.00		

## Concord

0520

142/116	DELTA DRIVE over I-93,US 4	Feb 2009	71.8	NHDOT	IB-C	38.6	192	4	Fed Br	NPR Y	16.14	1958
	<b>State Redlist</b>	Structurally Deficient	Over			710, 2005	28.0	Urban Local		Compact Highway		
			Road Under	NHS 49000, 2003		-3.3	Urban Interstate			Interstate Highway		
	Deck Poor. Was in Bow-Concord 13742. Not currently funded in the Ten Year Plan			Replace	Needs to be added to the Program					\$6,000,000.00		

163/106	I-93,FEE TPK over NH 9(LOUDON ROAD)	Feb 2009	38.6	Turnpike Bureau, NHDOT	IB-C	86.8	86	1	Fed Br	NPR Y	14.67	1966
	<b>State Redlist</b>	Structurally Deficient	Over	NHS 69000, 2002		74.0	Urban Interstate			Interstate Highway		
			Road Under	NHS 21000, 2005		-3.3	Urban Minor Arterial			Primary-DOT Maintained		
	Deck Serious, Substructure Poor. Project scope reduced to rehab.			Rehab	In the Program					\$2,400,000.00	2009	

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Concord

0520

203/087	NH 3A over I-93,FEE TPK	Dec 2008	42.2	Turnpike Bureau, NHDOT	IB-C	63.5	217	4	Fed Br	NPR Y	15.96	1957
	<b>State Redlist</b>	Structurally Deficient	Over			15000, 2006	52.0	Urban Minor Arterial		Secondary-Compact Maint.		
		Road Under	NHS			62000, 2003	-3.3	Urban Interstate		Interstate (Turnpike)		
	Deck and Substructure Poor. Project scope reduced to rehab.	Rehab		In the Program				\$4,000,000.00		2012		

## Conway

0540

167/067	EAST SIDE ROAD over SACO RIVER	Dec 2008	29.4	NHDOT	TB-C	18.8	227	2	Fed Br	03 Y	10.42	1890, 1989
Saco River Covered Br.	<b>State Redlist</b>	Structurally Deficient	Over			2400, 1992	18.1	Rural Min. Collector		Secondary-DOT Maintained		
	Covered Bridge, Posted 'Weight Limit 3 Tons'. Fire supression installation, 2002			Monitor and Keep in Service								

## Cornish

0550

064/108	CORNISH TOLL BR RD over CONNECTICUT RIVER	Nov 2008	24.8	NHDOT	TB-C	20.7	449	2	Fed Br	10 Y	9.42	1866, 1989
Cornish Windsor Covered	<b>State Redlist</b>	Structurally Deficient	Over			2700, 2003	19.5	Rural Mjr. Collector		Secondary-DOT Maintained		
	Covered Bridge, Posted 'Weight Limit 10 Tons'. Fire supression installation, 2002. Deck work completed 2007 by Bridge Maintenance.			Monitor and Keep in Service								

## Dover

0650

109/106	NH 9 over BMRR	Mar 2009	33.7	NHDOT	IB-C	31.1	75	2	Fed Br	NPR Y	17.25	1935
	<b>State Redlist</b>	Structurally Deficient	Over			9900, 2005	24.0	Urban Minor Arterial		Primary-DOT Maintained		
	Deck Serious. NH Recovery Project.	Replace		In the Program				\$6,785,000.00		2009		
182/123	GULF ROAD over SALMON FALLS RIVER	Nov 2008	48.7	NHDOT	IB-C	32.1	489	27	Fed Br	NPR Y		1982
	<b>State Redlist</b>	Structurally Deficient	Over			4900, 2003	29.5	Urban Collector		Secondary-DOT Maintained		
	Substructure Poor	Rehab		Needs to be added to the Program				\$13,000,000.00				

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Dover

0650

**200/023** ROAD over LITTLE BAY Nov 2008 \* 31.0 Turnpike Bureau, NHDOT HT 30.6 1585 9 Fed Br BRC Y 18.00 1934, 1950  
**General Sullivan Bridge** **State Redlist** Structurally Deficient *Over* 0, 2003 24.0 *Urban Local* Turnpike, not Primary  
 Serious Condition. Considered for Rehabilitation. Newington - Dover project under design, this bridge not funded in Ten Year Plan. Monitor and Keep in Service

## Durham

0700

**093/080** BENNETT ROAD over BMRR Mar 2009 44.9 NHDOT TB 21.5 33 1 Fed Br 10 Y 18.01 1910, 2003  
**State Redlist** Not Deficient *Over* 610, 2006 20.2 *Rural Local* Municipal Highway  
 Low Capacity, Posted 'Weight Limit 10 Tons'. Rehab by Bridge Maintenance, 2002. Waiting Municipal Action

## Easton

0720

**092/072** NH116 over MORSE BROOK Nov 2008 \* 52.4 NHDOT MP 59.1 10 1 NPR Y 1975  
**State Redlist** Not Applicable *Over* 280, 2005 23.0 *Rural Min. Collector* Secondary-DOT Maintained  
 Pipe in Serious Condition. Rehab To be addressed by Bridge Maintenance WTP

## Enfield

0770

**077/139** MAIN STREET over MASCOMA LAKE Nov 2008 17.7 NHDOT IB-C 27.4 323 5 Fed Br 15 Y 1938  
**Shaker Bridge** **State Redlist** Structurally Deficient *Over* 1200, 2003 21.0 *Rural Min. Collector* Secondary-DOT Maintained  
 Serious Condition. Posted 'Weight Limit 15 Tons'. Replace In the Program \$11,448,520.00 2010

## Epsom

0790

**160/110** NH107 over GRIFFIN BROOK Nov 2008 7.4 NHDOT CS 28.8 16 1 NPR Y 1933  
**State Redlist** Not Applicable *Over* 3000, 2004 26.4 *Rural Mjr. Collector* Secondary-DOT Maintained  
 Damaged in flooding 2007, abutment settled 9", shims in place. Replace In the Program \$900,000.00 2010

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Exeter

0820

<b>057/052</b>	NH111 over EXETER RIVER	Nov 2008	67.2	NHDOT	IB-C	36.0	38	1	Fed Br	NPR Y	1933, 1986
	<b>State Redlist</b> Abutment Undermined.	Structurally Deficient	Over	Rehab	8300, 2006	32.4	Rural Mjr. Collector			Secondary-DOT Maintained	WTP
					To be addressed by Bridge Maintenance						
<b>088/076</b>	PARK STREET over BMRR	Nov 2008	46.6	NHDOT	LT	26.6	63	1	Fed Br	10 Y	17.65 1900, 1929
	<b>State Redlist</b> Low Capacity, Posted 'Weight Limit 10 Tons'. Bridge Maintenance replaced floor and several steel members, 2002, 2003.	Structurally Deficient	Over		590, 2006	17.4	Urban Local			Compact Highway	
					Waiting Municipal Action						

## Farmington

0840

<b>096/140</b>	NH153 over COCHECO RIVER	Nov 2008	35.9	NHDOT	IB-C	40.5	48	2	Fed Br	NPR Y	1924
	<b>State Redlist</b> Poor Condition.	Structurally Deficient	Over	Replace	790, 2006	27.4	Rural Min. Collector			Secondary-DOT Maintained	
					Needs to be added to the Program				\$1,652,400.00		

## Francestown

0860

<b>079/089</b>	NH136 over BEAVER DAM BROOK	Nov 2008	61.6	NHDOT	CS	48.0	10	1		E1 Y	1926, 1980
	<b>State Redlist</b> Culvert Poor. Concrete Slab and Steel Pipe	Not Applicable	Over	Rehab	1300, 2006	32.0	Rural Mjr. Collector			Secondary-DOT Maintained	WTP
					To be addressed by Bridge Maintenance						

## Franklin

0880

<b>162/100</b>	NHRR(ABD) over NH127	Nov 2008	N/A	NHDOT	TPG	12.0	72	1	Fed Br	NPR Y	13.81 1928
	<b>State Redlist</b> Deck holed, Abutments Poor.	Not Applicable	Over	Remove	0, 2003	9.8	Rural Min. Collector			Undetermined / NA	
			Road Under		1800, 2004	39.4	Rural Mjr. Collector			Secondary-DOT Maintained	
					Needs to be added to the Program				\$500,000.00		

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Grafton

0990

130/126	US 4 over TEWKSBURY POND OUTLET	Nov 2008	63.0	NHDOT	CS	36.1	22	1	Fed Br	NPR Y	1928, 1983
	<b>State Redlist</b>	Structurally Deficient	Over			1900, 2002	32.3	Rural Minor Arterial		Primary-DOT Maintained	
	Slab Poor. CWIP			Rehab		To be addressed by Bridge Maintenance				2009	

## Hampton Falls

1100

162/044	NH 84 over HAMPTON FALLS RIVER	Mar 2009 *	53.9	NHDOT	MP	38.0	10	1		NPR Y	1961
	<b>State Redlist</b>	Not Applicable	Over			3200, 2006	27.4	Rural Local		Secondary-DOT Maintained	
	Poor Condition			Rehab		To be addressed by Bridge Maintenance				WTP	

## Hampton

1110

235/025	NH 1A over HAMPTON RIVER	Nov 2008	23.3	NHDOT	BAS	33.5	1199	13	Fed Br	E2 Y	1949, 1984
	<b>Neil R. Underwood Mem. State Redlist</b>	Structurally Deficient	Over			9239, 2007	26.0	Rural Minor Arterial		Secondary-DOT Maintained	
	Deck Poor. Mechanical and electrical repairs 2001, 2002, and 2003. Current Project: \$5,382,000.00 for rehab, \$3,750,000.00 for painting.			Rehab		In the Program				\$9,130,000.00	2009

## Hancock

1120

158/068	FORREST ROAD over CONTOOCOOK RIVER	Nov 2008	36.8	NHDOT	TB-C	26.0	88	1	Fed Br	08 Y	12.50	1937
	<b>County Bridge State Redlist</b>	Structurally Deficient	Over			1200, 2004	20.1	Rural Mjr. Collector		Secondary-DOT Maintained		
	Covered Bridge, Posted 'Weight Limit 8 Tons'. Fire supression installation, 2002					Monitor and Keep in Service						

## Harrisville

1150

056/058	CHESHAM ROAD over MINNEWAWA BROOK	Nov 2008	49.8	NHDOT	CS	27.0	90	3	Fed Br	NPR Y	1939
	<b>State Redlist</b>	Structurally Deficient	Over			1100, 2005	24.0	Rural Min. Collector		Secondary-DOT Maintained	
	Slab Poor.			Rehab		To be addressed by Bridge Maintenance				WTP	

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Harrisville

1150

068/072	CHESHAM ROAD over MINNEWAWA BROOK	Nov 2008 *	69.8	NHDOT	MP	59.1	15	1	NPR	Y	1963
	<b>State Redlist</b>	Not Applicable	Over			860, 2005	32.0	Rural Min. Collector	Secondary-DOT Maintained		
	Culvert Poor. CWIP			Rehab	To be addressed by Bridge Maintenance				2009		

## Haverhill

1170

215/158	MILL STREET over NHRR(ABD)	Nov 2008	25.5	NHDOT	TB	18.8	147	7	Fed Br	06	Y	1940
	<b>State Redlist</b>	Structurally Deficient	Over			100, 2005	16.6	Rural Local	Municipal Highway			
	Low Capacity, Posted 'Weight Limit 6 Tons'. Bridge maintenance looking at rehab. Had been programmed for 2005.			Rehab	Waiting Municipal Action							

## Hopkinton

1290

089/114	NH127 over SPILLWAY CHANNEL	Dec 2008	66.2	NHDOT	IB-C	32.0	280	3	Fed Br	NPR	Y	1961
	<b>State Redlist</b>	Structurally Deficient	Over			3400, 2006	24.0	Rural Mjr. Collector	Secondary-DOT Maintained			
	CWIP, closed to traffic.			Rehab	In the Program				\$1,284,408.00	2008		

## Jackson

1320

148/050	NH 16A over ELLIS RIVER	Dec 2008	32.2	NHDOT	TB-C	25.8	121	1	Fed Br	03	Y	9.55	1876, 2004
	<b>Honeymoon Covered Bridge</b>	<b>State Redlist</b>	Not Deficient	Over		2600, 2003	15.7	Rural Min. Collector	Secondary-DOT Maintained				
	Covered Bridge, Posted 'Weight Limit 3 Tons'. Rehab 2004				Monitor and Keep in Service								

## Jefferson

1350

046/178	US 2 over ISRAEL RIVER	Oct 2008	57.0	NHDOT	IB-C	46.6	164	2	Fed Br	NPR	Y	1974
	<b>State Redlist</b>	Structurally Deficient	Over	NHS		3200, 2006	42.5	Rural Princ. Arterial	Primary-DOT Maintained			
	Deck Poor.			Rehab	Needs to be added to the Program				\$2,000,000.00			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Keene

1360

**129/099** NH 9,NH 10 over ELM STREET Mar 2009 68.6 NHDOT IB-C 52.9 76 1 Fed Br NPR Y 14.70 1978  
**State Redlist** Structurally Deficient Over NHS 8100, 2003 48.8 Urban Principal Arterial Primary-DOT Maintained  
 Deck Poor. Rehab Needs to be added to the \$1,000,000.00 Program

## Laconia

1390

**126/163** CENTENARY AVENUE over NHRR Nov 2008 2.0 NHDOT TB 22.6 121 7 Fed Br 07 Y 17.75 1940  
**State Redlist** Structurally Deficient Over 230, 2006 16.5 Rural Local Municipal Highway  
 Low Capacity, Poor Condition. Posted 'Weight Limit 7 Tons'. Monitor and Keep in Service

## Lancaster

1410

**140/120** NHRR over CEMETERY STREET Jul 2008 N/A NHDOT TPG 9.8 29 1 Fed Br NPR Y 8.32 1930  
**State Redlist** Not Applicable Over 0, 1980 9.8 Rural Local Undetermined / NA  
 Road Under 100, 1986 20.7 Rural Local Municipal Highway  
 Ties in Poor Condition Rehab To be addressed by Rail and Transit WTP

## Landaff

1420

**137/031** NH116 over DAVIS BROOK Nov 2008 \* 54.9 NHDOT MP 85.3 11 1 NPR Y 1961  
**State Redlist** Not Applicable Over 310, 2006 31.0 Rural Min. Collector Secondary-DOT Maintained  
 Poor Condition Rehab To be addressed by Bridge Maintenance WTP

## Lebanon

1440

**058/127** US 4 over CONNECTICUT RIVER Sep 2008 0.0 NHDOT HT 26.0 392 3 Fed Br 10 Y 13.78 1936, 1976  
**State Redlist** Structurally Deficient Over 14000, 2005 24.0 Urban Minor Arterial Secondary-Compact Maint.  
 Deck and Superstructure Serious. Bridge Maintenance Steel Replace In the Program \$5,250,000.00 2009  
 Repairs 2005. NH Recovery Project to install Temporary Bridge  
 2009, \$4,500,000.00.

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Lebanon

1440

156/117	I-89 NB over HARDY HILL ROAD	Jun 2008	65.2	NHDOT		IB-C	42.3	45	1	Fed Br	NPR Y	13.86	1966
	<b>State Redlist</b> Structurally Deficient Over Deck Poor.			NHS	14000, 2005		38.0	Rural Interstate			Interstate Highway		
				Rehab	In the Program					\$2,000,000.00	2010		
188/126	US 4 over NHRR(ABD),MASCOMA RIVER	Nov 2008	34.7	NHDOT		DPG	31.0	463	6	Fed Br	E2 Y		1930, 1957
	<b>State Redlist</b> Structurally Deficient Over Deck and Floorbeams Poor.				13000, 2007		26.0	Rural Minor Arterial			Primary-DOT Maintained		
				Replace	In the Program					\$10,900,000.00	2011		
192/129	PAYNE ROAD over NHRR(ABD)	Nov 2008	88.5	NHDOT		TB	18.0	54	2	Fed Br	15 Y		1946, 2004
	<b>State Redlist</b> Not Deficient Over Low Capacity, Posted 'Weight Limit 15 Tons'.				150, 2005		16.0	Rural Local			Secondary-DOT Maintained		
					Monitor and Keep in Service								

## Lincoln

1480

149/110	FLUME BUS ROUTE over PEMIGEWASSET RIVER	Nov 2008	43.3	NHDRED		TB-C	16.3	52	1	Fed Br	15 Y	7.84	1886
	<b>Flume Covered Bridge</b> <b>State Redlist</b> Structurally Deficient Over Covered Bridge, Low Capacity (Flume Bus use Only).				50, 2000		16.2	Rural Local			Undetermined / NA		
					Monitor and Keep in Service								

## Lisbon

1500

094/114	US302,NH 10 over AMMONOOSUC RIVER	Nov 2008	58.6	NHDOT		IB-C	46.5	304	3	Fed Br	NPR Y		1979
	<b>State Redlist</b> Structurally Deficient Over Deck Poor.				5200, 2005		42.5	Rural Minor Arterial			Primary-DOT Maintained		
				Rehab	In the Program					\$1,791,385.00	2009		

## Littleton

1530

105/135	I-93 NB over CONNECTICUT RIVER	Oct 2008	61.7	NHDOT		IB-C	44.8	670	4	Fed Br	NPR Y		1976
	<b>Sen. Andrew Poulsen Br.</b> <b>State Redlist</b> Structurally Deficient Over Deck Poor.			NHS	2972, 2007		40.5	Rural Interstate			Interstate Highway		
				Rehab	In the Program					\$6,000,000.00	2017		

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Littleton

1530

<b>200/137</b>	NH135	over	COW BROOK	Nov 2008 *	50.1	NHDOT		MP	85.3	10	1	NPR	Y	1973
			<b>State Redlist</b>	Not Applicable	Over				3100, 2007	32.2	Rural Min. Collector		Secondary-DOT Maintained	
			Pipe in Poor condition.			Rehab		To be addressed by Bridge Maintenance					WTP	

## Londonderry

1540

<b>096/163</b>	I-93 SB	over	BMRR(ABD)	Mar 2009	28.0	NHDOT		IB-C	47.8	142	3	Fed Br	NPR	Y	20.58	1962
			<b>State Redlist</b>	Structurally Deficient	Over		NHS	75000, 2006	42.0	Rural Interstate			Interstate Highway			
			Deck Serious.			Replace		In the Program				\$3,000,000.00	2010			
<b>097/163</b>	I-93 NB	over	BMRR(ABD)	Mar 2009	32.0	NHDOT		IB-C	51.8	150	3	Fed Br	NPR	Y	21.08	1962
			<b>State Redlist</b>	Structurally Deficient	Over		NHS	75000, 2006	46.0	Rural Interstate			Interstate Highway			
			Deck and Substructure Serious.			Replace		In the Program				\$3,000,000.00	2010			
<b>099/160</b>	I-93 SB	over	NH 28	Mar 2009	43.0	NHDOT		IB-C	43.8	153	3	Fed Br	NPR	Y	16.55	1962
			<b>State Redlist</b>	Structurally Deficient	Over		NHS	65000, 2006	38.0	Rural Interstate			Interstate Highway			
			Deck Serious.			Replace		In the Program				\$3,000,000.00	2010			
<b>100/160</b>	I-93 NB	over	NH 28	Mar 2009	52.1	NHDOT		IB-C	43.8	150	3	Fed Br	NPR	Y	17.00	1962
			<b>State Redlist</b>	Structurally Deficient	Over		NHS	6500, 2006	38.0	Rural Interstate			Interstate Highway			
			Deck Serious.			Replace		In the Program				\$3,000,000.00	2010			

## Manchester

1610

<b>060/086</b>	I-93 SB	over	RD, BMRR, MERRIMACK RIVER	Dec 2008	58.1	NHDOT		IB-C	68.8	826	4	Fed Br	NPR	Y	23.29	1976
			<b>State Redlist</b>	Structurally Deficient	Over		NHS	59500, 2007	64.5	Urban Interstate			Interstate Highway			
			Deck Poor.			Rehab		In the Program				\$3,000,000.00	2009			
<b>107/066</b>	NORTH RAMP	over	I-293, FEE TPK	Oct 2008	55.0	Turnpike Bureau, NHDOT		IB-C	48.0	92	2	Fed Br	NPR	Y	17.81	1957
			<b>State Redlist</b>	Structurally Deficient	Over		NHS	16000, 2007	40.0	Urban Interstate			Compact Highway			
			Substructure Poor.			Road Under	NHS	42000, 2003	-3.3	Urban Interstate			Interstate (Turnpike)			
						Rehab		To be addressed by Bridge Maintenance					WTP			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Manchester

1610

ID	Description	Over	Under	Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC	over/under	Year Built
144/066	I-293,FEE TPK	over	N BR PISCATAQUOG RIVER	Mar 2009	49.1	Turnpike Bureau, NHDOT	IB-C	84.9	148	3	Fed Br	NPR	Y	1957
	<b>State Redlist</b>		Structurally Deficient	Over		NHS 67000, 2003		72.0	Urban Interstate				Interstate (Turnpike)	
	Deck and Substructure Poor.					Rehab In the Program					\$7,710,000.00		2013	
146/064	I-293,FEE TPK	over	S BR PISCATAQUOG RIVER	Mar 2009	62.0	Turnpike Bureau, NHDOT	IB-C	69.8	213	3	Fed Br	NPR	Y	1957
	<b>State Redlist</b>		Structurally Deficient	Over		NHS 67000, 2003		60.0	Urban Interstate				Interstate (Turnpike)	
	Deck Poor.					Rehab In the Program					\$7,710,000.00		2013	
146/065	I-293,FEE TPK SPUR	over	S BR PISCATAQUOG RIVER	Mar 2009	64.0	Turnpike Bureau, NHDOT	IB-C	25.8	216	3	Fed Br	NPR	Y	1957
	<b>State Redlist</b>		Structurally Deficient	Over		NHS 67000, 2003		20.0	Urban Interstate				Interstate (Turnpike)	
	Deck Poor.					Rehab In the Program					\$7,710,000.00		2013	
149/063	I-293,FEE TPK	over	SPUR D	Mar 2009	59.8	Turnpike Bureau, NHDOT	IB-C	73.8	149	3	Fed Br	NPR	Y	16.42 1957
	<b>State Redlist</b>		Structurally Deficient	Over		NHS 67000, 2003		62.0	Urban Interstate				Interstate (Turnpike)	
				Road Under		NHS 6000, 1992		-3.3	Urban Interstate				Interstate (Turnpike)	
	Deck Poor.					Rehab In the Program					\$7,710,000.00		2013	
153/061	I-293 RAMP	over	I-293,FEE TPK	Mar 2009	67.1	Turnpike Bureau, NHDOT	IB-C	25.8	252	4	Fed Br	NPR	Y	16.08 1956
	<b>State Redlist</b>		Structurally Deficient	Over		NHS 67000, 2003		20.0	Urban Interstate				Interstate (Turnpike)	
				Road Under		NHS 67000, 2003		-3.3	Urban Interstate				Interstate (Turnpike)	
	Deck Poor.					Rehab In the Program					\$7,710,000.00		2013	
166/124	ISLAND POND ROAD	over	I-93 SB,I-293 WB	Mar 2009	11.7	NHDOT	IB-C	38.0	170	3	Fed Br	C1	Y	16.33 1961
	<b>State Redlist</b>		Structurally Deficient	Over		4600, 2005		30.0	Urban Collector				Compact Highway	
				Road Under		NHS 71000, 2003		-3.3	Urban Interstate				Interstate Highway	
	Deck Serious, Substructure Poor. CWIP. Closed To Traffic.					Replace In the Program					\$3,727,064.00		2008	
166/125	ISLAND POND ROAD	over	I-93 NB,I-293 EB	Mar 2009	11.7	NHDOT	IB-C	38.0	170	3	Fed Br	C1	Y	16.80 1961
	<b>State Redlist</b>		Structurally Deficient	Over		4600, 2005		30.0	Urban Collector				Compact Highway	
				Road Under		NHS 71000, 2005		-3.3	Urban Interstate				Interstate Highway	
	Deck Serious, Substructure Poor. CWIP. Closed To Traffic.					Replace In the Program					\$3,727,064.00		2008	

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Merrimack

1680

111/115	FEE TPK over	SOUHEGAN RIVER	Mar 2009	42.3	Turnpike Bureau, NHDOT	IB-C	92.5	229	3	Fed Br	NPR Y	1953
<b>Merrill's Marauders Br.</b>	<b>State Redlist</b>	Structurally Deficient	Over		NHS 59400, 2006		91.5	Rural Princ. Arterial		Primary-Turnpike Maint.		
	Deck and Substructure Poor.	Deck and Substructure Poor.	CWIP.		Rehab	In the Program			\$15,499,331.00	2008		

## Milton

1730

101/110	OLD NH 16B over	JONES BROOK	Nov 2008	47.5	NHDOT	CRF	27.7	28	1	Fed Br	E2 Y	1932
	<b>State Redlist</b>	Structurally Deficient	Over		1500, 2005		24.0	Rural Local		Secondary-DOT Maintained		
	Scour exists at abutments				Rehab	To be addressed by Bridge Maintenance				2009		

## Nashua

1770

115/120	BALDWIN STREET over	BMRR	Mar 2009 *	35.9	NHDOT	TB	13.0	73	3	Fed Br	06 Y	18.00 1935
	<b>State Redlist</b>	Functionally Obsolete	Over		1800, 2006		12.7	Urban Local		Compact Highway		
	Low Capacity, Posted 'Weight Limit 6 Tons'. Part of the Broad Sreet Parkway Project, Municipally Managed, scheduled for 2011, estimated cost \$4684764.00.				Replace	Waiting Municipal Action				2011		

## New Boston

1790

103/103	NH 13 over	S BR PISCATAQUOG RIVER	Nov 2008	29.9	NHDOT	CRF	31.3	62	1	Fed Br	NPR Y	1947
	<b>State Redlist</b>	Structurally Deficient	Over		5400, 2006		23.9	Rural Mjr. Collector		Secondary-DOT Maintained		
	Poor Condition.				Rehab	To be addressed by Bridge Maintenance				WTP		

## New Castle

1810

066/071	NH 1B over	LITTLE HARBOR	Nov 2008	16.2	NHDOT	BAS	30.8	253	6	Fed Br	E2 Y	1942, 1975
	<b>State Redlist</b>	Structurally Deficient	Over		3200, 2005		24.0	Urban Minor Arterial		Primary-DOT Maintained		
	Monitor Exposed Steel Piles, Pile Repair by Bridge Maintenance, Contract Paint in 2000, some holes in stringers. Pile repair project 2009 (\$1,558,700.00).				Rehab	In the Program			\$4,750,000.00	2013		

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Newfields

1830

130/083	NEW ROAD over BMRR	Mar 2009	34.9	NHDOT		TB	18.9	41	2	Fed Br	06	Y	17.92	1930, 1985
	<b>State Redlist</b>	Structurally Deficient	Over				500, 2005	16.8	Rural Local				Municipal Highway	
	Low Capacity, Posted 'Weight Limit 6 Tons'.						Waiting Municipal Action							

## New Hampton

1840

240/104	SMITHS CROSSING over NHRR	Nov 2008 *	18.3	NHDOT		TB	16.0	82	3	Fed Br	06	N	20.50	1940
	<b>State Redlist</b>	Structurally Deficient	Over				0, 2008	14.5	Rural Local				Unmaintained Highway	
	Deck Serious. Low Capacity, Posted 'Weight Limit 6 Tons'.						Monitor and Keep in Service							

## New Ipswich

1860

113/074	SMITHVILLE ROAD over WEST BR SOUHEGAN RIVER	Nov 2008 *	52.9	NHDOT		MP	68.9	12	1		NPR	Y		1971
	<b>State Redlist</b>	Not Applicable	Over				850, 2005	28.5	Rural Min. Collector				Secondary-DOT Maintained	
	Rusting of Corrugated Steel Pipe. Temporary span in place, installed 2006.			Replace			To be addressed by Bridge Maintenance						2009	
157/093	NH123,NH124 over SOUHEGAN RIVER	Nov 2008	40.0	NHDOT		IB-C	30.2	135	9	Fed Br	E2	Y		1900, 1957
<b>High Bridge</b>	<b>State Redlist</b>	Structurally Deficient	Over				4600, 2006	24.0	Rural Mjr. Collector				Secondary-DOT Maintained	
	Poor Condition.			Replace			In the Program						\$2,900,000.00	2012

## New London

1880

124/058	I-89 SB over KING HILL ROAD	Nov 2008	70.0	NHDOT		IB-C	43.8	88	1	Fed Br	NPR	Y	16.67	1967
	<b>State Redlist</b>	Structurally Deficient	Over		NHS		9000, 2007	38.0	Rural Interstate				Interstate Highway	
				Road Under	NHS		4200, 2005	-3.3	Rural Princ. Arterial				Secondary-DOT Maintained	
	Deck Poor. CWIP			Rehab			In the Program						\$600,000.00	2008
124/059	I-89 NB over KING HILL ROAD	Nov 2008	68.0	NHDOT		IB-C	43.8	88	1	Fed Br	NPR	Y	16.42	1967
	<b>State Redlist</b>	Structurally Deficient	Over		NHS		9000, 2007	38.0	Rural Interstate				Interstate Highway	
				Road Under	NHS		4200, 2005	-3.3	Rural Princ. Arterial				Secondary-DOT Maintained	
	Deck Serious. CWIP			Rehab			In the Program						\$600,000.00	2008

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Newton

1930

<b>064/107</b>	POND ROAD over BMRR	Mar 2009	25.0	NHDOT	TB	25.0	41	1	Fed Br	08	Y	17.58	1920, 2003
	<b>State Redlist</b>	Not Deficient	Over			780, 2005	20.9	Rural Local				Municipal Highway	
	Low Capacity, Posted 'Weight Limit 8 Tons'. Bridge Maintenance replaced deck and stringers, 2003.				Waiting Municipal Action								

## North Hampton

1970

<b>130/064</b>	CEDAR ROAD over BMRR	Mar 2009	54.8	NHDOT	TB	21.0	34	1	Fed Br	11	Y	17.45	1920, 2002
	<b>State Redlist</b>	Not Deficient	Over			2200, 2005	19.0	Rural Local				Municipal Highway	
	Low Capacity, Posted 'Weight Limit 11 Tons'. Repairs by Bridge Maintenance 2002.				Waiting Municipal Action								

## Ossipee

2040

<b>137/297</b>	NH 16,NH 25 over BEARCAMP RIVER	Nov 2008	11.4	NHDOT	IB-C	33.2	396	5	Fed Br	NPR	Y		1955
	<b>State Redlist</b>	Structurally Deficient	Over	NHS		11000, 2007	28.0	Rural Princ. Arterial				Primary-DOT Maintained	
	Superstructure Poor.			Rehab		In the Program					\$3,000,000.00	2016	
<b>137/299</b>	NH 16,NH 25 over RELIEF BEARCAMP RIVER	Nov 2008	33.2	NHDOT	IB-C	33.2	172	4	Fed Br	NPR	Y		1955
	<b>State Redlist</b>	Structurally Deficient	Over	NHS		11000, 2007	28.0	Rural Princ. Arterial				Primary-DOT Maintained	
	Poor Deck and Substructure.			Rehab		In the Program					\$2,000,000.00	2016	
<b>152/268</b>	NH 16,NH 25 over LOVELL RIVER	Nov 2008	53.7	NHDOT	IB-C	34.5	62	1	Fed Br	C2	Y		1950
	<b>State Redlist</b>	Structurally Deficient	Over	NHS		11000, 2007	31.0	Rural Princ. Arterial				Primary-DOT Maintained	
	Deck Poor. Also listed for Betterment Funding in 2009.			Rehab		In the Program					\$1,000,000.00	2016	

## Pelham

2050

<b>110/090</b>	MAIN STREET over BEAVER BROOK	Nov 2008	15.8	NHDOT	MA	35.7	46	2	Fed Br	E2	Y		1900, 1929
	<b>State Redlist</b>	Structurally Deficient	Over			4900, 2006	29.9	Rural Local				Secondary-DOT Maintained	
	Monitor Stonework, Poor Condition			Replace		Needs to be added to the Program					\$2,000,000.00		

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Peterborough

2080

<b>087/077</b>	US202,NH101	over	CONTOOCOOK RIVER	Nov 2008	63.0	NHDOT	IB-C	43.8	195	3	Fed Br	NPR Y	1958
			<b>State Redlist</b>	Structurally Deficient	Over			14000, 2005	40.8	Rural Minor Arterial		Primary-DOT Maintained	
			Deck Poor.			Rehab		In the Program			\$2,000,000.00	2018	

## Pinkhams Grant

2095

<b>069/080</b>	PATROL SHED ROAD	over	STONY BROOK	Nov 2008 *	36.0	NHDOT	IB-W	20.5	23	1		NPR Y	1945, 1996
			<b>State Redlist</b>	Not Applicable	Over			0, 2000	18.0	Rural Local		Undetermined / NA	
			Poor timber deck. Steel plates in place.			Rehab		To be addressed by Bridge Maintenance				2009	

## Pittsburg

2100

<b>099/034</b>	MURPHY DAM ROAD	over	DAM SPILLWAY	Nov 2008	40.1	NHDES	BGB	20.5	38	1	Fed Br	15 Y	1938
			<b>State Redlist</b>	Structurally Deficient	Over			10, 2000	17.0	Rural Mjr. Collector		Municipal Highway	
			Low Capacity, Posted 'Weight Limit 15 Tons'.					Monitor and Keep in Service					

## Plymouth

2160

<b>117/143</b>	NH 25,NH 3A	over	BAKER RIVER	Nov 2008	32.4	NHDOT	IB-C	49.7	259	3	Fed Br	NPR Y	1968
			<b>State Redlist</b>	Structurally Deficient	Over			11000, 2007	44.0	Rural Minor Arterial		Primary-DOT Maintained	
			Deck Poor.			Rehab		In the Program			\$2,000,000.00	2015	

## Portsmouth

2170

<b>154/101</b>	NH 33	over	BMRR	Nov 2008	2.0	NHDOT	IB-C	32.0	45	1	Fed Br	E2 Y	17.09 1930
			<b>State Redlist</b>	Structurally Deficient	Over			18000, 2003	23.1	Urban Minor Arterial		Primary-Compact Maint.	
			Serious Condition. Municipally Managed Project. Construction underway.			Replace		In the Program			\$8,817,937.00	2008	

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Portsmouth

2170

173/071	US 1 SB over US 1 BYPASS	Nov 2008	53.0	NHDOT		IB-C	26.0	182	4	Fed Br	NPR Y	14.80	1940
	<b>State Redlist</b>	Structurally Deficient	Over	NHS	4800, 2005		22.5	Urban Principal Arterial				Primary-DOT Maintained	
			Road Under	NHS	21000, 2004		-3.3	Urban Expressway				Turnpike, not Primary	
	Deck Poor.			Remove	In the Program					\$2,000,000.00	2013		
183/087	NH 33 over US 1 BYPASS	Nov 2008	37.9	NHDOT		IB-C	30.1	123	4	Fed Br	NPR Y	15.39	1940
	<b>State Redlist</b>	Structurally Deficient	Over	NHS	6200, 2006		23.8	Urban Minor Arterial				Primary-Compact Maint.	
			Road Under	NHS	21000, 2004		-3.3	Urban Expressway				Turnpike, not Primary	
	Deck Poor.			Replace	In the Program					\$2,000,000.00	2013		
188/097	ISLINGTON STREET over US 1 BYPASS	Nov 2008	26.0	NHDOT		IB-C	31.7	123	4	Fed Br	NPR Y	15.29	1940
	<b>State Redlist</b>	Structurally Deficient	Over		8300, 2005		24.0	Urban Collector				Compact Highway	
			Road Under	NHS	23000, 2003		-3.3	Urban Expressway				Turnpike, not Primary	
	Deck Poor.			Replace	In the Program					\$2,000,000.00	2013		
205/116	WOODBURY AVENUE over US 1 BYPASS	Nov 2008	61.1	NHDOT		CRF	52.0	90	1	Fed Br	NPR Y	12.07	1950
	<b>State Redlist</b>	Structurally Deficient	Over		7300, 2004		40.0	Urban Minor Arterial				Primary-Compact Maint.	
			Road Under	NHS	14000, 2003		-3.3	Urban Expressway				Turnpike, not Primary	
	Poor Condition.			Replace	In the Program					\$2,000,000.00	2013		
211/114	STARK STREET over US 1 BYPASS	Nov 2008	48.4	NHDOT		IB-C	30.7	123	4	Fed Br	NPR Y	15.29	1940
	<b>State Redlist</b>	Structurally Deficient	Over		60, 2007		20.0	Urban Local				Compact Highway	
			Road Under	NHS	14000, 2004		-3.3	Urban Expressway				Turnpike, not Primary	
	Deck Poor.			Replace	In the Program					\$2,000,000.00	2012		
227/112	MAPLEWOOD AVENUE over US 1 BYPASS	Nov 2008	20.3	NHDOT		IB-C	30.1	161	4	Fed Br	NPR Y	15.29	1940
	<b>State Redlist</b>	Structurally Deficient	Over		9800, 2006		21.7	Urban Collector				Compact Highway	
			Road Under	NHS	14000, 2004		-3.3	Urban Expressway				Turnpike, not Primary	
	Deck Poor.			Rehab	In the Program					\$2,000,000.00	2012		
247/084	US 1 over PISCATAQUA RIVER	Nov 2008	6.0	NHDOT		LIFT	29.0	1201	13	Fed Br	20 Y	17.67	1921, 1982
	<b>Memorial Bridge</b>	<b>State Redlist</b>	Structurally Deficient	Over			11000, 2003	28.0	Urban Minor Arterial			Primary-DOT Maintained	
		Serious Condition. Partial Structural Repairs 2004. Partial counterweight rope replacement 2008. Rehab Bid 2008 - too high. No current advertising date. Condition and Needs Studies Underway.		Rehab	In the Program					\$60,000,000.00			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Portsmouth

2170

251/108	US 1 BYPASS	over	PISCATAQUA RIVER & RR	Nov 2008	12.8	Interstate Bridge Auth.	LIFT	36.0	2804	27	Fed Br	NPR Y	16.08	16.70	1940, 1991
<b>Sarah M. Long Bridge</b>	<b>State Redlist</b>		Structurally Deficient	Over		NHS	14000, 2004	30.0	Urban Expressway		Turnpike, not Primary				
			Deck Poor. Permanent electrical repairs 2008. Included in Transportation needs study.			Rehab	In the Program				\$35,500,000.00	2012			

## Randolph

2180

080/043	US 2	over	MOOSE RIVER	Nov 2008 *	26.0	NHDOT	MP	124.7	11	1		NPR Y			1966
	<b>State Redlist</b>		Not Applicable	Over		NHS	5400, 2005	50.0	Rural Princ. Arterial		Primary-DOT Maintained				
			Culvert Poor.			Rehab	To be addressed by Bridge Maintenance					WTP			

## Raymond

2190

083/154	DUDLEY ROAD	over	LAMPREY RIVER	Nov 2008	21.4	NHDOT	CS	21.0	52	2	Fed Br	106 Y			1914, 1972
	<b>State Redlist</b>		Structurally Deficient	Over			630, 2007	18.0	Rural Local		Secondary-DOT Maintained				
			Substructure in Serious condition. Wings Settled, Posted 'Weight Limit 10 Tons'.				Monitor and Keep in Service								

## Rochester

2220

109/090	NH 11	over	US202,NH 16,SP TPK	Feb 2008	56.3	Turnpike Bureau, NHDOT	IB-C	48.0	198	4	Fed Br	NPR Y		16.01	1958
	<b>State Redlist</b>		Structurally Deficient	Over		NHS	21000, 2004	40.0	Urban Principal Arterial		Primary-DOT Maintained				
			Deck Poor.			Road Under	19000, 1994	39.4	Urban Minor Arterial		Primary-Turnpike Maint.				
						Rehab	In the Program				\$4,900,000.00	2009			
157/110	NH 16,SP TPK NB	over	NH125	Nov 2008	35.6	Turnpike Bureau, NHDOT	IB-C	47.3	153	3	Fed Br	NPR Y		16.96	1957
	<b>State Redlist</b>		Structurally Deficient	Over		NHS	15500, 2007	42.0	Urban Expressway		Primary-Turnpike Maint.				
			Deck and Substructure Serious. CWIP.			Road Under	NHS 19000, 2005	-3.3	Urban Minor Arterial		Secondary-DOT Maintained				
						Replace	In the Program				\$16,886,000.00	2009			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Rochester

2220

158/110	NH 16,SP TPK SB over NH125	Nov 2008	24.5	Turnpike Bureau, NHDOT	IB-C	47.8	153	3	Fed Br	NPR Y	15.68	1957
	<b>State Redlist</b>	Structurally Deficient	Over	NHS 27000, 2005		42.0	Urban Expressway			Primary-Turnpike Maint.		
			Road Under	NHS 18000, 2001		-3.3	Urban Minor Arterial			Secondary-DOT Maintained		
	Deck and Substructure Serious. CWIP			Replace	In the Program				\$13,258,570.00	2008		

159/113	SP TPK OFF RAMP over WARDLEY BROOK	Nov 2008 *	69.9	Turnpike Bureau, NHDOT	MP	75.0	15	1		NPR Y		1957
	<b>State Redlist</b>	Not Applicable	Over	NHS 500, 1991		28.0	Urban Expressway			Primary-Turnpike Maint.		
	Pipe in Poor condition. CWIP. Closed To Traffic.			Replace	In the Program				\$700,000.00	2009		

## Rollinsford

2230

069/046	OAK STREET over BMRR	Nov 2008	20.2	NHDOT	LT	26.5	65	1	Fed Br	06 Y	17.67	1890, 1928
	<b>State Redlist</b>	Structurally Deficient	Over	8000, 2004		22.7	Urban Minor Arterial			Compact Highway		
	Posted 'Weight Limit 6 Tons'. Bridge Maintenance replaced all timbers 2007			Waiting Municipal Action								

## Rye

2260

252/156	NH 1A over SEAVEYS CREEK	Mar 2009 *	47.1	NHDOT	TB	30.0	145	8	Fed Br	BRC Y		1943
	<b>State Redlist</b>	Structurally Deficient	Over	5600, 2004		22.0	Rural Mjr. Collector			Primary-DOT Maintained		
	Poor Condition. CWIP. Closed To Traffic.			Replace	In the Program				\$2,574,385.00	2008		

## Salem

2280

068/078	I-93 SB over NH 97(PELHAM RD)	Nov 2008	23.3	NHDOT	IB-C	47.8	127	3	Fed Br	NPR Y	15.49	1961
	<b>State Redlist</b>	Structurally Deficient	Over	NHS 41500, 2006		42.0	Rural Interstate			Interstate Highway		
	Serious Condition.			Replace	In the Program				\$6,050,000.00	2012		

070/079	I-93 NB over NH 97(PELHAM ROAD)	Nov 2008	24.3	NHDOT	IB-C	43.8	134	3	Fed Br	NPR Y	15.19	1961
	<b>State Redlist</b>	Structurally Deficient	Over	NHS 41500, 2006		38.0	Rural Interstate			Interstate Highway		
	Deck and Substructure Poor.			Replace	In the Program				\$6,050,000.00	2012		

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Salem

2280

<b>073/063</b>	I-93 SB over NH 38	Feb 2009	25.6	NHDOT		IB-C	43.8	139	3	Fed Br	NPR Y	14.14	1961
	<b>State Redlist</b> Structurally Deficient Over Serious Condition.			NHS	41500, 2006		38.0	Rural Interstate			Interstate Highway		
				Replace	In the Program					\$9,900,000.00	2011		
<b>077/063</b>	I-93 NB over NH 38	Feb 2009	26.6	NHDOT		IB-C	43.8	142	3	Fed Br	NPR Y	14.40	1961
	<b>State Redlist</b> Structurally Deficient Over Deck Serious.			NHS	43500, 2003		38.0	Rural Interstate			Interstate Highway		
				Replace	In the Program					\$9,900,000.00	2011		
<b>081/055</b>	I-93(RAMP B) over I-93 SB	Feb 2009	48.2	NHDOT		IB-C	43.0	163	3	Fed Br	NPR Y	16.11	1965
	<b>State Redlist</b> Structurally Deficient Over Deck Serious. CWIP			NHS	14700, 2005		35.5	Rural Interstate			Interstate Highway		
				Road Under NHS	43500, 2003		-3.3	Rural Interstate			Interstate Highway		
				Replace	In the Program					\$3,381,862.00	2007		
<b>082/057</b>	I-93(RAMP B) over I-93 NB	Feb 2009	58.2	NHDOT		IB-C	43.0	155	3	Fed Br	NPR Y	17.67	1965
	<b>State Redlist</b> Structurally Deficient Over Deck Serious.			NHS	14700, 2005		35.5	Rural Interstate			Interstate Highway		
				Road Under NHS	42500, 2001		-3.3	Urban Interstate			Interstate Highway		
				Replace	In the Program					\$3,381,862.00	2007		
<b>082/061</b>	I-93(RAMP B) over SOUTH POLICY ROAD	Feb 2009	64.2	NHDOT		IB-C	43.0	146	3	Fed Br	NPR Y	17.85	1960
	<b>State Redlist</b> Structurally Deficient Over Deck Serious.				3300, 2003		38.0	Urban Minor Arterial			Interstate Highway		
				Replace	In the Program					\$3,381,862.00	2007		
<b>083/061</b>	I-93(RAMP D) over SOUTH POLICY ROAD	Feb 2009	45.3	NHDOT		IB-C	26.7	146	3	Fed Br	NPR Y	18.34	1965
	<b>State Redlist</b> Structurally Deficient Over Deck Poor.				3300, 2003		20.0	Urban Minor Arterial			Interstate Highway		
				Replace	In the Program					\$3,381,862.00	2007		

## Sanbornton

2310

<b>127/099</b>	I-93 NB over SALMON BROOK	Nov 2008 *	58.0	NHDOT		CB	91.9	28	1	Fed Br	NPR Y		1962
	<b>State Redlist</b> Structurally Deficient Over Poor areas in Concrete Box.			NHS	12500, 2004		38.0	Rural Interstate			Interstate Highway		
				Rehab	Needs to be added to the Program					\$500,000.00			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Seabrook

2340

136/071	BMRR(ABD) over WALTON ROAD	Mar 2009	N/A	NHDOT	IB-W	10.0	24	1	Fed Br	NPR Y	12.47	1931
	<b>State Redlist</b>	Not Applicable	Over			0, 1980	9.8	Rural Local		Undetermined / NA		
			Road Under			1100, 2004	19.7	Rural Local		Secondary-DOT Maintained		
	Overheight collision damage to girder. Hit again in 2007. Hit again in 2008.				Remove	To be addressed by Rail and Transit				WTP		

## Springfield

2390

091/048	GEORGES MILLS ROAD over STAR LAKE OUTLET	Oct 2008	70.0	NHDOT	MP	72.0	12	2		NPR Y		1970
	<b>State Redlist</b>	Not Applicable	Over			500, 2008	52.0	Rural Local		Secondary-DOT Maintained		
	Pipe in Poor condition.			Rehab		To be addressed by Bridge Maintenance				WTP		

## Stewartstown

2410

054/163	BRIDGE STREET over CONNECTICUT RIVER	Oct 2008	14.6	NHDOT	SA	30.5	232	9	Fed Br	10 Y		1930, 1971
	<b>State Redlist</b>	Structurally Deficient	Over			1500, 2005	24.0	Rural Min. Collector		Secondary-DOT Maintained		
	Poor Condition, America's Most Beautiful Steel Bridge, 1935, Class C. Posted 'Weight Limit 10 tons'			Rehab		Needs to be added to the Program				\$6,000,000.00		
121/114	NH145 over BISHOP BROOK	Nov 2008	8.3	NHDOT	IB-C	23.0	42	1	Fed Br	C2 Y		1940
	<b>State Redlist</b>	Structurally Deficient	Over			850, 2004	20.0	Rural Min. Collector		Secondary-DOT Maintained		
	Substructure in Serious Condition.			Replace		In the Program				\$1,800,000.00	2016	

## Stoddard

2420

129/109	NH123 over DEAD BROOK	Nov 2008 *	33.4	NHDOT	MP	62.3	10	2		NPR Y		1972
	<b>State Redlist</b>	Not Applicable	Over			800, 2003	28.0	Rural Mjr. Collector		Secondary-DOT Maintained		
	Pipe in Poor condition.			Rehab		To be addressed by Bridge Maintenance				WTP		

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Stratham

2450

075/114	NH 33 EB,NH108 NB over MILL BROOK	Mar 2009 *	71.2	NHDOT	MP	62.0	11	1		NPR Y	1955
	<b>State Redlist</b> Pipe in Poor condition.	Not Applicable	Over	Rehab	16000, 2007 To be addressed by Bridge Maintenance	42.0	Rural Minor Arterial			Primary-DOT Maintained 2009	

## Sullivan

2460

093/061	NH 9 over OTTER BROOK	Nov 2008	2.0	NHDOT	CTB	27.8	92	2	Fed Br	NPR Y	1932
	<b>State Redlist</b> Superstructure Poor. 2005 flood damage repaired.	Structurally Deficient	Over	Replace	NHS 7000, 2005 Needs to be added to the Program	25.3	Rural Princ. Arterial			Primary-DOT Maintained \$2,200,000.00	

## Swanzey

2510

149/072	NH 32 over MARTIN BROOK	Mar 2009	41.7	NHDOT	CS	23.7	27	1	Fed Br	E1 Y	1929
	<b>State Redlist</b> Poor Condition.	Structurally Deficient	Over	Rehab	2800, 2007 To be addressed by Bridge Maintenance	21.5	Rural Mjr. Collector			Secondary-DOT Maintained WTP	
150/056	NH 32 over MARTIN BROOK	Mar 2009	49.5	NHDOT	CS	25.0	16	1		NPR Y	1928, 1972
	<b>State Redlist</b> Poor Condition.	Not Applicable	Over	Rehab	2800, 2007 To be addressed by Bridge Maintenance	22.0	Rural Mjr. Collector			Secondary-DOT Maintained WTP	
167/175	SWANZEY FACTORY RD over TROY BROOK	Mar 2009 *	72.7	NHDOT	MP	62.3	12	1		NPR Y	1970
	<b>State Redlist</b> Pipe in Poor condition.	Not Applicable	Over	Rehab	2600, 2007 To be addressed by Bridge Maintenance	28.0	Rural Local			Secondary-DOT Maintained WTP	

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt Year

Redlist Note

## Temple

2530

<b>094/114</b>	NH101	over	BLOOD BROOK	Nov 2008	41.9	NHDOT	CS	51.0	24	1	Fed Br	NPR Y	1930
			<b>State Redlist</b>	Structurally Deficient	Over	NHS	8024, 2007	47.5	Rural Princ. Arterial			Primary-DOT Maintained	
			Poor Condition.			Rehab	To be addressed by Bridge Maintenance					WTP	
<b>107/051</b>	NH 45	over	MILLER GAMBLE BROOK	Nov 2008 *	69.9	NHDOT	MP	134.5	13	1		NPR Y	1968
			<b>State Redlist</b>	Not Applicable	Over		1300, 2007	30.0	Rural Min. Collector			Secondary-DOT Maintained	
			Steel Culvert in Poor Condition			Rehab	To be addressed by Bridge Maintenance					WTP	

## Thornton

2540

<b>175/076</b>	CROSS ROAD	over	PEMIGEWASSET RIVER	Nov 2008	59.1	NHDOT	IB-C	36.0	417	4	Fed Br	NPR Y	1973
	<b>Thornton Memorial Bridge</b>		<b>State Redlist</b>	Structurally Deficient	Over		770, 2007	28.0	Rural Local			Secondary-DOT Maintained	
			Deck Poor.			Rehab	Needs to be added to the Program				\$3,000,000.00		

## Wakefield

2610

<b>093/039</b>	NH 16	over	PINE BROOK	May 2008 *	54.6	NHDOT	MP-A	40.0	19	1		NPR Y	1956
			<b>State Redlist</b>	Not Applicable	Over	NHS	9100, 2005	40.6	Rural Princ. Arterial			Primary-DOT Maintained	
			Pipe in Serious Condition.			Rehab	To be addressed by Bridge Maintenance					WTP	

## Walpole

2620

<b>062/052</b>	BRIDGE STREET	over	CONNECTICUT RIVER	Nov 2008	2.3	NHDOT	CA	32.5	230	2	Fed Br	106 Y	1930, 1974
	<b>Vilas Bridge</b>		<b>State Redlist</b>	Structurally Deficient	Over		4600, 2003	24.0	Rural Mjr. Collector			Primary-DOT Maintained	
			Serious Condition. Closed to traffic March 19, 2009.			Rehab	In the Program				\$3,290,000.00	2015	

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Warner

2630

ID	Route	Span	Structure	Insp Date	FSR	Owner	Type	Width	Length	Spans	Weight	VC	over/under	Year Built
144/056	NH103 over WARNER RIVER	Nov 2008	59.9	NHDOT	TPG	32.0	81	1	Fed Br	C2	Y		1936	
	<b>State Redlist</b>	Structurally Deficient	Over			4000, 2004	28.3	Rural Mjr. Collector		Primary-DOT Maintained				
	Deck Poor. New paint 2006.				Rehab	To be addressed by Bridge Maintenance					2009			
164/104	I-89 NB over NH103	Nov 2008	75.8	NHDOT	IB-C	48.0	90	1	Fed Br	NPR	Y	16.37	1968, 1993	
	<b>State Redlist</b>	Structurally Deficient	Over		NHS	9000, 2007	44.5	Rural Interstate		Interstate Highway				
			Road Under			7800, 2006	49.2	Rural Mjr. Collector		Primary-DOT Maintained				
	Deck Poor. Partial deck repairs in 2008.				Rehab	Needs to be added to the Program				\$800,000.00				
254/180	NH127 over WARNER RIVER	Nov 2008	51.4	NHDOT	IB-C	28.2	123	3	Fed Br	C2	Y		1937	
	<b>State Redlist</b>	Structurally Deficient	Over			1600, 2006	25.1	Rural Mjr. Collector		Secondary-DOT Maintained				
	Deck Poor.				Rehab	Needs to be added to the Program				\$800,000.00				

## Weare

2670

116/036	NH 77 over HILLSIDE BROOK	Nov 2008 *	68.9	NHDOT	MP	82.0	13	2		NPR	Y		1951
	<b>State Redlist</b>	Not Applicable	Over			2500, 2007	23.0	Rural Mjr. Collector		Secondary-DOT Maintained			
	Poor Culvert.				Rehab	To be addressed by Bridge Maintenance				WTP			

## Wentworth

2690

146/090	NH 25,NH118 over BAKER RIVER	Nov 2008	61.4	NHDOT	IB-C	44.0	204	3	Fed Br	NPR	Y		1960
	<b>State Redlist</b>	Structurally Deficient	Over			3600, 2007	40.0	Rural Minor Arterial		Primary-DOT Maintained			
	Deck Poor.				Rehab	Needs to be added to the Program				\$2,000,000.00			

# NHDOT Redlist Summary

Bridge Data --> Insp Date FSR Owner Type Width Length Spans Weight VC over/under Year Built  
 Road Data --> AADT, Year Status Width Functional Class NH System / Class & Rebuilt

Redlist Note

## Wilton

2770

129/126	NH 31	over	SOUHEGAN RIVER	Dec 2008	50.3	NHDOT	IB-C	38.5	80	1	Fed Br	NPR Y	1971
			<b>State Redlist</b>	Structurally Deficient	Over			5200, 2004	30.0	Rural Mjr. Collector		Secondary-DOT Maintained	
			Deck Serious.			Rehab		Needs to be added to the Program			\$750,000.00		

## Winchester

2790

065/102	NH119	over	BROAD BROOK	Nov 2008	54.0	NHDOT	CRF	41.0	21	1	E2 Y	1930	
			<b>State Redlist</b>	Not Applicable	Over			3200, 2004	39.0	Rural Mjr. Collector		Primary-DOT Maintained	
			Poor Condition. CWIP.			Rehab		To be addressed by Bridge Maintenance				2009	

113/077	NH119	over	ASHUELOT RIVER	Nov 2008	67.5	NHDOT	IB-C	43.5	194	3	Fed Br	NPR Y	1962
			<b>State Redlist</b>	Structurally Deficient	Over			3700, 2007	40.0	Rural Mjr. Collector		Primary-DOT Maintained	
			Deck Poor.			Rehab		Needs to be added to the Program			\$2,500,000.00		

152/181	NH 10	over	ASHUELOT RIVER	Nov 2008	23.8	NHDOT	IB-C	31.3	181	3	Fed Br	NPR Y	1935
			<b>State Redlist</b>	Structurally Deficient	Over			7200, 2004	24.0	Rural Minor Arterial		Primary-DOT Maintained	
			Deck Poor.			Replace		In the Program			\$4,160,000.00	2011	

## Windham

2800

134/101	I-93 SB	over	NH111	Nov 2008	63.1	NHDOT	IB-C	43.8	168	3	Fed Br	NPR Y	19.69 1961
			<b>State Redlist</b>	Structurally Deficient	Over	NHS		36829, 2005	38.0	Rural Interstate		Interstate Highway	
			Deck Serious.			Replace		In the Program			\$4,000,000.00	2012	

135/090	I-93 SB	over	NH111A	Nov 2008	63.8	NHDOT	IB-C	43.8	160	3	Fed Br	NPR Y	14.99 1961
			<b>State Redlist</b>	Structurally Deficient	Over	NHS		77000, 2006	38.0	Rural Interstate		Interstate Highway	
			Deck Serious.			Replace		In the Program			\$4,000,000.00	2012	

**Total Bridge Count: 139**