

NEW HAMPSHIRE DEPARTMENT OF TRANSPORTATION
BUREAU OF TRANSPORTATION PLANNING
ACCIDENT STATISTICS GROUP

ACCIDENT LOCATION STUDY NUMBER : 08-32

PREPARED FOR: TRENT ZANES, HIGHWAY DESIGN
PROJECT: BEDFORD 13527

PREPARED BY: PAUL YEATON, PLANNING

SITE LOCATION: US RTE 3 FROM BACK RIVER RD TO HAWTHORNE DR

DATA SOURCE: STATE POLICE, LOCAL POLICE AND MOTORIST ACCIDENT REPORTS
SUBMITTED TO AND ENTERED BY THE NEW HAMPSHIRE DEPT. OF SAFETY

SUMMARY OF ACCIDENT DATA
STUDY PERIOD: NOV 2002 - DEC 2007

FATAL ACCIDENTS	:	0	INJURY ACCIDENTS	:	4	PROPERTY DAMAGE ONLY ACCIDENTS	:	19
FATALITIES	:	0	INJURIES	:	4	TOTAL ACCIDENTS	:	23
INJURIES IN FATALS	:	0						

THERE ARE NO FATAL ACCIDENTS

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

03 001721	0 INJURIES	1 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	SNOW/SLUSH
01 02 0509			FIXED OBJECT-GUARD RAIL	NONE	DARK-STREET LIGHT ON
THU	S RIVER RD		ALONG THE ROAD	CURVE AND GRADE	SNOW
100FN	STATION RD		UNKNOWN OR OTHER	NORMAL	/45NONE
01	OPERATOR		LEFT FRONT	ILLEGAL/UNSAFE SPEED	
	AUTOMOBILE		FOLLOWING ROADWAY	NO APPARENT DEFECT	
	NORTH		NO APPARENT OBSCUREMENT		

03 002916	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
01 15 0848			OTHER MV	NONE	DAYLIGHT
WED	S RIVER RD		ALONG ROAD AT DRIVEWAY ACCESS	STRAIGHT AND UPGRADE	CLEAR
75FS	BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30VISIBLE ROAD MARKINGS
01	OPERATOR		FRONT	DRIVER INATTENTION/DISTRACTION	
	AUTOMOBILE		FOLLOWING ROADWAY	NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		REAR	NO IMPROPER DRIVING	
	AUTOMOBILE		MAKING RIGHT TURN	NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT		

03 003431	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
01 20 0950			OTHER MV	NONE	DAYLIGHT
MON	S RIVER RD		ALONG ROAD AT DRIVEWAY ACCESS	STRAIGHT AND UPGRADE	CLEAR
100FS	BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30VISIBLE ROAD MARKINGS
01	OPERATOR		LEFT FRONT	FAILURE TO YIELD R-O-W	
	AUTOMOBILE		MAKING LEFT TURN	NO APPARENT DEFECT	
	EAST		OTHER VEHICLE		
02	OPERATOR		RIGHT FRONT	NO IMPROPER DRIVING	
	AUTOMOBILE		FOLLOWING ROADWAY	NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT		

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

03 008286	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	SNOW/SLUSH
02 17 1911		OTHER MV		NONE	DARK-STREET LIGHT ON
MON	282 SOUTH RIVER RD		ALONG THE ROAD	STRAIGHT AND LEVEL	SNOW
	@ 7 SUNSET LANE		SIDESWIPE COLLISION	NORMAL	/45VISIBLE ROAD MARKINGS
01	OPERATOR		LEFT FRONT		ILLEGAL/UNSAFE SPEED
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	NORTH		BLOWING SAND/SNOW/RAIN		
02	OPERATOR		LEFT FRONT		NO IMPROPER DRIVING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		BLOWING SAND/SNOW/RAIN		

03 015671	0 INJURIES	1 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
05 14 1116		FIXED OBJECT-EMBANKMENT/DITCH/CURB	NONE		DAYLIGHT
WED	S RIVER RD		ALONG THE ROAD	STRAIGHT AND UPGRADE	CLOUDY
	500FN BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30NONE
01	OPERATOR		NOT CODED		UNKNOWN
	AUTOMOBILE		PASSING ON RIGHT		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

03 018547	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	WET
06 11 1418		OTHER MV		NONE	DAYLIGHT
WED	233 S RIVER RD		ALONG THE ROAD	STRAIGHT AND LEVEL	RAIN
	200FN STATION RD		REAR END COLLISION	NORMAL	/45VISIBLE ROAD MARKINGS
01	OPERATOR		REAR		NO IMPROPER DRIVING
	AUTOMOBILE		SLOWING OR STOPPING		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		FRONT		DRIVER INEXPERIENCE
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

03 023304	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	WET
07 16 1335		OTHER MV		NONE	DAYLIGHT
WED	288 S RIVER RD		AT INTERSECTION	STRAIGHT AND LEVEL	CLOUDY
@	9 CEDARWOOD DR		REAR END COLLISION	NORMAL	/45VISIBLE ROAD MARKINGS
01	OPERATOR		FRONT		DRIVER INATTENTION/DISTRACTION
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY		NO APPARENT DEFECT
	NORTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		REAR		NO IMPROPER DRIVING
	AUTOMOBILE		MAKING LEFT TURN		NO APPARENT DEFECT
	NORTH		NO APPARENT OBSCUREMENT		

03 025920	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	WET
08 12 1045		OTHER MV		ROADWAY UNDER MAINTENANCE	DAYLIGHT
TUE	S RIVER RD		INTERSECTON RELATED	STRAIGHT AND UPGRADE	RAIN
75FN	STATION RD		UNKNOWN OR OTHER	NORMAL	/45VISIBLE ROAD MARKINGS
01	OPERATOR		FRONT		FOLLOWING TOO CLOSE
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		REAR		NO IMPROPER DRIVING
	AUTOMOBILE		SLOWING OR STOPPING		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

03 026885	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
08 18 0952			THROWN/FALLING OBJ	NONE	DAYLIGHT
MON	196 S RIVER RD		ALONG THE ROAD	STRAIGHT AND LEVEL	CLEAR
@	1 BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30 VISIBLE ROAD MARKINGS
01	OPERATOR		FRONT		NO IMPROPER DRIVING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		NOT CODED		OTHER
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

03 026895	0 INJURIES	1 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
08 31 0903			ANIMAL	NONE	DAYLIGHT
SUN	233 S RIVER RD		AT INTERSECTION	STRAIGHT AND UPGRADE	CLEAR
@	0 STATION RD		UNKNOWN OR OTHER	NORMAL	/45 VISIBLE ROAD MARKINGS
01	OPERATOR		FRONT		NO IMPROPER DRIVING
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

03 029182	1 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
09 16 2238			OTHER MV	NONE	DARK-STREET LIGHT ON
TUE	196 S RIVER RD		INTERSECTON RELATED	CURVE AND LEVEL	CLEAR
@	1 BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30 TRAFFIC SIGNALS
01	OPERATOR		LEFT FRONT DOOR		IMPROPER/UNSAFE LANE USE
	AUTOMOBILE		CHANGING LANES/MERGING		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		FRONT		NO IMPROPER DRIVING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

03	031006	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
10	08 1612		OTHER MV		NONE	DAYLIGHT
WED	233 SOUTH RIVER RD		ALONG THE ROAD	STRAIGHT AND LEVEL	CLEAR	
	75FN	0 STATION RD	UNKNOWN OR OTHER	NORMAL	/45NONE	
01	OPERATOR		REAR		NO IMPROPER DRIVING	
	AUTOMOBILE		SLOWING OR STOPPING		NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT			
02	OPERATOR		FRONT		DRIVER INATTENTION/DISTRACTION	
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY		NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT			

04	007222	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
03	11 0716		OTHER MV		NONE	DAYLIGHT
THU	SO RIVER RD		ALONG THE ROAD	STRAIGHT AND LEVEL	NO ADVERSE CONDITIONS	
	200FS	NO HAWTHORNE DR	REAR END COLLISION	WORN	/45VISIBLE ROAD MARKINGS	
01	OPERATOR		REAR		NO IMPROPER DRIVING	
	AUTOMOBILE		SLOWING OR STOPPING		NO APPARENT DEFECT	
	NORTH		NO APPARENT OBSCUREMENT			
02	OPERATOR		FRONT		OTHER	
	AUTOMOBILE		SLOWING OR STOPPING		NO APPARENT DEFECT	
	NORTH		NO APPARENT OBSCUREMENT			

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

04 012294	0 INJURIES	3 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	WET
04 26 1421		OTHER MV		NONE	DAYLIGHT
MON	SOUTH RIVER RD		ALONG THE ROAD	STRAIGHT AND UPGRADE	RAIN
400FN	STATION RD		UNKNOWN OR OTHER	NORMAL	/45VISIBLE ROAD MARKINGS
01	UNIDENTIFIED		NOT CODED	IMPROPER TURN	
	PICK-UP/LIGHT TRUCK		MAKING U-TURN	OTHER DEFECT	
	SOUTH		NOT CODED		
02	OPERATOR		REAR	NO IMPROPER DRIVING	
	UTILITY VEHICLE(4X4)		FOLLOWING ROADWAY	NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT		
03	OPERATOR		FRONT	OTHER	
	AUTOMOBILE		FOLLOWING ROADWAY	NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT		

04 014400	0 INJURIES	1 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
05 30 0048		ANIMAL		NONE	DARK-NO STREET LIGHT
SUN	S RIVER RD		ALONG THE ROAD	STRAIGHT AND UPGRADE	CLEAR
400FS	BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30VISIBLE ROAD MARKINGS
01	OPERATOR		FRONT	NO IMPROPER DRIVING	
	AUTOMOBILE		FOLLOWING ROADWAY	NO APPARENT DEFECT	
	NORTH		NO APPARENT OBSCUREMENT		

04 016284	1 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
06 09 1625		OTHER MV		NONE	DAYLIGHT
WED	289 S RIVER RD		AT INTERSECTION	STRAIGHT AND LEVEL	CLEAR
@	70 HAWTHORNE DR		SO.UNKNOWN OR OTHER	NORMAL	/45VISIBLE ROAD MARKINGS
01	OPERATOR		LEFT REAR	FAILURE TO YIELD R-O-W	
	AUTOMOBILE		STARTING FROM PARKED	NO APPARENT DEFECT	
	EAST		NO APPARENT OBSCUREMENT		
02	OPERATOR		LEFT REAR	NO IMPROPER DRIVING	
	AUTOMOBILE		FOLLOWING ROADWAY	NO APPARENT DEFECT	

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		
	SOUTH		NO APPARENT OBSCUREMENT		

04 028445	1 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	WET
10 14 1602			OTHER MV	NONE	DAYLIGHT
THU	282 SOUTH RIVER RD	AT INTERSECTION		STRAIGHT AND LEVEL	RAIN
@	7 SUNSET LANE	UNKNOWN OR OTHER		NORMAL	/45 VISIBLE ROAD MARKINGS
01	OPERATOR		LEFT REAR		NO IMPROPER DRIVING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		FRONT		NO IMPROPER DRIVING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

04 031582	1 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	WET
11 04 2144			BICYCLIST	NONE	DARK-STREET LIGHT ON
THU	196 SOUTH RIVER RD	AT INTERSECTION		CURVE AND LEVEL	RAIN
25FS	BACK RIVER RD	COLLISION AT RIGHT ANGLE		NORMAL	/30 STOP SIGN
01	OPERATOR		LEFT FRONT		FAILURE TO YIELD R-O-W
	OTHER		STOPPED IN TRAFFIC		NO APPARENT DEFECT
	UNKNOWN		BLOWING SAND/SNOW/RAIN		
02	BICYCLIST		FRONT		DEFECTIVE EQUIPMENT
	OTHER		FOLLOWING ROADWAY		FRONT/REAR LIGHTING DEFECTIVE
	SOUTH		NO APPARENT OBSCUREMENT		

06 001155	0 INJURIES	1 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	SNOW/SLUSH
01 08 0954			FIXED OBJECT-TRAFFIC SIGNAL	NONE	DAYLIGHT
SUN	S RIVER RD	ALONG THE ROAD		CURVE AND LEVEL	SNOW
500FS	BACK RIVER RD	UNKNOWN OR OTHER		NORMAL	/30 VISIBLE ROAD MARKINGS
01	OPERATOR		RIGHT FRONT		ILLEGAL/UNSAFE SPEED
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	NORTH		ICE/SNOW ETC. ON WINDOW/GLASS		

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

06 020575	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
08 27 1249		OTHER MV		NONE	DAYLIGHT
SUN	222 S RIVER RD		INTERSECTON RELATED	STRAIGHT AND UPGRADE	CLOUDY
600FS	BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/30TRAFFIC SIGNALS
01	OPERATOR		RIGHT FRONT		DISREGARD TRAFFIC CONTROL DEVICE
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		
02	OPERATOR		LEFT FRONT		NO IMPROPER DRIVING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	NORTH		NO APPARENT OBSCUREMENT		

06 014598	0 INJURIES	1 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
08 29 0005		FIXED OBJECT-SIGN POST		NONE	DARK-STREET LIGHT ON
TUE	S RIVER RD		ALONG THE ROAD	STRAIGHT AND UPGRADE	CLEAR
500FS	BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/45OTHER
01	OPERATOR		LEFT REAR DOOR		DISREGARD TRAFFIC CONTROL DEVICE
	OTHER		MAKING U-TURN		NO APPARENT DEFECT
	SOUTH		NO APPARENT OBSCUREMENT		

06 033176	0 INJURIES	2 VEH	BEDFORD	OTHER	SNOW/SLUSH
12 30 1215		OTHER MV		NONE	DAYLIGHT
SAT	S RIVER RD		ALONG THE ROAD	STRAIGHT AND UPGRADE	SNOW
100FS	BACK RIVER RD		UNKNOWN OR OTHER	NORMAL	/UNTRAFFIC SIGNALS
01	OPERATOR		REAR		NO IMPROPER DRIVING
	AUTOMOBILE		STOPPED IN TRAFFIC		NO APPARENT DEFECT
	EAST		NO APPARENT OBSCUREMENT		
02	OPERATOR		FRONT		SKIDDING
	AUTOMOBILE		FOLLOWING ROADWAY		NO APPARENT DEFECT
	EAST		NO APPARENT OBSCUREMENT		

YR CASE	# INJURIES	# VEH	TOWN	ROAD: DESIGN	CONDITION: SURFACE
DATE TIME			TYPE OF ACCIDENT	ADDITIONAL FEATURES	LIGHTING
DAY	LOCATION		LOCATION 1ST EVENT	ALIGNMENT	WEATHER
			DIAGRAM CODE	CONDITION/POSTED SPEED	TRAFFIC CONTROLS
UNIT #	UNIT TYPE		IMPACT POINT	APPARENT CONTRIBUTING FACTORS	
	VEHICLE TYPE		APPARENT PRE-ACCIDENT VEHICLE ACTION	VEHICLE DEFECTS	
	DIRECTION		VISION OBSCUREMENT		

07	033932	0 INJURIES	2 VEH	BEDFORD	UNDIVIDED ROAD, 2-WAY TRAFFIC	DRY
12	09 1215		OTHER MV		NONE	DAYLIGHT
SUN	S RIVER RD		INTERSECTON RELATED	CURVE AND GRADE	CLOUDY	
	75FS	BACK RIVER RD	UNKNOWN OR OTHER	NORMAL	/30	VISIBLE ROAD MARKINGS
01	OPERATOR		REAR		NO IMPROPER DRIVING	
	AUTOMOBILE		STOPPED IN TRAFFIC		NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT			
02	OPERATOR		FRONT		OTHER	
	UTILITY VEHICLE(4X4)		OTHER VEHICLE ACTION		NO APPARENT DEFECT	
	SOUTH		NO APPARENT OBSCUREMENT			