GRAIN-SIZE DISTRIBUTION TEST REPORT



% Coarse	% Sand	% Silt	% Clay
3.7%	60.1%	30.8%	5.3%

Soil Counter	Borehole ID	Sample ID	Depth Upper	Depth Lower	Date Sampled	Texture	Soil Description	PL	LL	PI
596645461	JI1750	TR-S10	ft	ft		SM	Silty sand			

NP=No plastic limit

Company: Thielsch Engineering
Address: 195 Frances Ave.
Crantson RI 02910
Country: United States
Telephone: 401-467-6454 **Fax:** 401-467-2398

Project No.: 07-0002-6 **Borehole:** JI1750
Project Name: Louis Berger
Location:
Soil Counter: 596645461 **Sample ID:** TR-S10
Depth: ft

USCS GRAIN-SIZE DISTRIBUTION

Tested By:
Test Date: 18-Apr-07